

Macon, MO



Legend

- Manhole
- Manhole Label
- Lift Station
- Lamp Hole
- Cleanout
- Lamphole
- Lamp Hole Label
- Grit Chamber
- Pipe Point
- Pipe Point Label
- Gravity Main
- Gravity Main Label
- Pressurized Main Point
- Air Release Valve
- ◆ GPS Location
- Trace Station
- Valve
- Pressurized Main
- Lagoon
- Road
 - County Roads / City Streets
 - US Highway
 - Lettered State Highway
- Railroad
- Address
- Parcel

Notes

1

200.0 0 100.00 200.0 Feet

1 in. = 100ft. ▲

This Cadastral Map is for informational purposes only. It does not purport to represent a property boundary survey of the parcels shown and shall not be used for conveyances or the establishment of property boundaries.

THIS MAP IS NOT TO BE USED FOR NAVIGATION

Upstream Manhole: C5-001

Rim Elevation: 784.88 Ft

Integrity™ Sewer Analyst

Downstream Manhole: C3-040

Rim Elevation: 776.85 Ft

Sewer Report

Material: Block

Depth: 6.94 Ft

Slope (%): 1.98

Line Length: 399.56 Ft

Line Size: 8"

Material: Block

Depth: 6.95 Ft


Pipe Material: Clay



Pipe Invert Elevation: 777.94 Ft


Pipe Invert Elevation: 770.01 Ft

Macon, MO



- Legend**
- Manhole
 - Manhole Label
 - Lift Station
 - Lamp Hole
 - Cleanout
 - Lamphole
 - Lamp Hole Label
 - Grit Chamber
 - Pipe Point
 - Pipe Point Label
 - Gravity Main
 - Gravity Main Label
 - Pressurized Main Point
 - Air Release Valve
 - ◆ GPS Location
 - Trace Station
 - Valve
 - Pressurized Main
 - Lagoon
 - Road
 - County Roads / City Streets
 - US Highway
 - Lettered State Highway
 - Railroad
 - Address
 - Parcel

1 in. = 100ft.



This Cadastral Map is for informational purposes only. It does not purport to represent a property boundary survey of the parcels shown and shall not be used for conveyances or the establishment of property boundaries.

THIS MAP IS NOT TO BE USED FOR NAVIGATION

Notes
2

Upstream Manhole: C5-062

Rim Elevation: 791.69 Ft

Integrity™ Sewer Analyst

Downstream Manhole: C5-001

Rim Elevation: 784.88 Ft

Sewer Report

Material: Block

Depth: 11.53 Ft

Slope (%): 1.10

Line Length: 192.55 Ft

Line Size: 8"

Material: Block


Depth: 6.94 Ft

Pipe Material: Clay




Pipe Invert Elevation: 780.16 Ft

Pipe Invert Elevation: 778.05 Ft




Macon, MO



Legend

- Manhole
- Manhole Label
- Lift Station
- Lamp Hole
- Cleanout
- Lamphole
- Lamp Hole Label
- Grit Chamber
- Pipe Point
- Pipe Point Label
- Gravity Main
- Gravity Main Label
- Pressurized Main Point
- Air Release Valve
- ◆ GPS Location
- Trace Station
- Valve
- Pressurized Main
- Lagoon
- Road
 - County Roads / City Streets
 - US Highway
 - Lettered State Highway
- + Railroad
- Address
- Parcel

1 in. = 100ft.



This Cadastral Map is for informational purposes only. It does not purport to represent a property boundary survey of the parcels shown and shall not be used for conveyances or the establishment of property boundaries.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Notes
3

Upstream Manhole: C5-065

Rim Elevation: 792.48 Ft

Integrity™ Sewer Analyst

Downstream Manhole: C5-062

Rim Elevation: 791.69 Ft

Sewer Report

Material: Block

Depth: 10.20 Ft

Slope (%): 0.99

Line Length: 209.45 Ft

Line Size: 8"

Material: Block


Depth: 11.53 Ft

Pipe Material: Clay




Pipe Invert Elevation: 782.28 Ft

Pipe Invert Elevation: 780.20 Ft



Macon, MO



- Legend**
- Manhole
 - Manhole Label
 - Lift Station
 - Lamp Hole
 - Cleanout
 - Lamphole
 - Lamp Hole Label
 - Grit Chamber
 - Pipe Point
 - Pipe Point Label
 - Gravity Main
 - Gravity Main Label
 - Pressurized Main Point
 - Air Release Valve
 - ◆ GPS Location
 - Trace Station
 - Valve
 - Pressurized Main
 - Lagoon
 - Road
 - County Roads / City Streets
 - US Highway
 - Lettered State Highway
 - +— Railroad
 - Address
 - Parcel

1 in. = 100ft.



This Cadastral Map is for informational purposes only. It does not purport to represent a property boundary survey of the parcels shown and shall not be used for conveyances or the establishment of property boundaries.
 THIS MAP IS NOT TO BE USED FOR NAVIGATION

Notes
4

Upstream Manhole: C5-066

Rim Elevation: 795.18 Ft

Integrity™ Sewer Analyst

Downstream Manhole: C5-065

Rim Elevation: 792.48 Ft

Sewer Report

Material: Block

Depth: 8.02 Ft

Slope (%): 1.20

Line Length: 399.41 Ft

Line Size: 8"

Material: Block


Depth: 10.20 Ft

Pipe Material: Clay





Pipe Invert Elevation: 787.16 Ft

Pipe Invert Elevation: 782.36 Ft



Macon, MO




Legend

- Manhole
- Manhole Label
- Lift Station
- Lamp Hole
- Cleanout
- Lamphole
- Lamp Hole Label
- Grit Chamber
- Pipe Point
- Pipe Point Label
- Gravity Main
- Gravity Main Label
- Pressurized Main Point
- Air Release Valve
- GPS Location
- Trace Station
- Valve
- Pressurized Main
- Lagoon
- Road**
- County Roads / City Streets
- US Highway
- Lettered State Highway
- Railroad
- Address
- Parcel

Notes

5



This Cadastral Map is for informational purposes only. It does not purport to represent a property boundary survey of the parcels shown and shall not be used for conveyances or the establishment of property boundaries.

THIS MAP IS NOT TO BE USED FOR NAVIGATION

Upstream Manhole: C5-068

Rim Elevation: 797.65 Ft

Integrity™ Sewer Analyst

Downstream Manhole: C5-066

Rim Elevation: 795.18 Ft

Sewer Report

Material: **Precast**

Depth: 7.54 Ft

Slope (%): 0.76

Line Length: 379.55 Ft

Line Size: 8"

Material: **Block**


Depth: 8.02 Ft

Pipe Material: **Clay**



Pipe Invert Elevation: 790.11 Ft

Pipe Invert Elevation: 787.24 Ft



Macon, MO



Legend

- Manhole
- Manhole Label
- Lift Station
- Lamp Hole
- Cleanout
- Lamphole
- Lamp Hole Label
- Grit Chamber
- Pipe Point
- Pipe Point Label
- Gravity Main
- Gravity Main Label
- Pressurized Main Point
- Air Release Valve
- GPS Location
- Trace Station
- Valve
- Pressurized Main
- Lagoon
- Fire Hydrant
- Water Valve
- Water Control Valve
- <all other values>
- Blowoff
- Curb Stop
- Water Meter

Notes

6

This Cadastral Map is for informational purposes only. It does not purport to represent a property boundary survey of the parcels shown and shall not be used for conveyances or the establishment of property boundaries.

THIS MAP IS NOT TO BE USED FOR NAVIGATION

Upstream Manhole: E5-108

Rim Elevation: 862.01 Ft

Integrity™ Sewer Analyst

Downstream Manhole: E5-106

Rim Elevation: 848.12 Ft

Sewer Report

Material: Block

Depth: 5.37 Ft

Slope (%): 8.27

Line Length: 199.47 Ft

Line Size: 8"

Material: Block


Depth: 8.48 Ft

Pipe Material: Clay




Pipe Invert Elevation: 856.64 Ft

Pipe Invert Elevation: 840.14 Ft




Macon, MO



- ### Legend
- Manhole
 - Manhole Label
 - Lift Station
 - Lamp Hole
 - Cleanout
 - Lamphole
 - Lamp Hole Label
 - Grit Chamber
 - Pipe Point
 - Pipe Point Label
 - Gravity Main
 - Gravity Main Label
 - Pressurized Main Point
 - Air Release Valve
 - ◆ GPS Locallion
 - Trace Station
 - Valve
 - Pressurized Main
 - Lagoon
 - + Fire Hydrant
 - + Water Valve
 - Water Control Valve
 - <all other values>
 - Blowoff
 - Curb Stop
 - Water Meter

1 in. = 100ft.



This Cadastral Map is for informational purposes only. It does not purport to represent a property boundary survey of the parcels shown and shall not be used for conveyances or the establishment of property boundaries.

THIS MAP IS NOT TO BE USED FOR NAVIGATION

Notes

7

Upstream Manhole: E5-105

Rim Elevation: 834.38 Ft

Integrity™ Sewer Analyst

Downstream Manhole: E3-019

Rim Elevation: 814.94 Ft

Sewer Report

Material: Block

Depth: 12.40 Ft

Slope (%): 9.30

Line Length: 148.94 Ft

Line Size: 8"

Material: Precast


Depth: 6.93 Ft

Pipe Material: Clay



Pipe Invert Elevation: 821.98 Ft

Pipe Invert Elevation: 808.13 Ft



Macon, MO



- ### Legend
- Manhole
 - Manhole Label
 - Lift Station
 - Lamp Hole
 - Cleanout
 - Lamphole
 - Lamp Hole Label
 - Grit Chamber
 - Pipe Point
 - Pipe Point Label
 - Gravity Main
 - Gravity Main Label
 - Pressurized Main Point
 - Air Release Valve
 - ◆ GPS Location
 - Trace Station
 - Valve
 - Pressurized Main
 - Lagoon
 - + Fire Hydrant
 - + Water Valve
 - + Water Control Valve
 - <all other values>
 - Blowoff
 - Curb Stop
 - Water Meter

1 in. = 100ft.



This Cadastral Map is for informational purposes only. It does not purport to represent a property boundary survey of the parcels shown and shall not be used for conveyances or the establishment of property boundaries.
THIS MAP IS NOT TO BE USED FOR NAVIGATION

Notes

8

Upstream Manhole: E5-106

Rim Elevation: 848.12 Ft

Integrity™ Sewer Analyst

Downstream Manhole: E5-105

Rim Elevation: 834.38 Ft

Sewer Report

Material: Block

Depth: 8.48 Ft

Slope (%): 7.11

Line Length: 244.23 Ft

Line Size: 8"

Material: Block


Depth: 12.40 Ft

Pipe Material: Clay



Pipe Invert Elevation: 839.64 Ft

Pipe Invert Elevation: 822.27 Ft



Upstream Manhole: G3-073

Rim Elevation: 854.37 Ft

Integrity™ Sewer Analyst

Downstream Manhole: G3-072

Rim Elevation: 853.42 Ft

Sewer Report

Material: Block

Depth: 6.75 Ft

Slope (%): 0.70

Line Length: 299.68 Ft

Line Size: 8"

Material: Block


Depth: 8.32 Ft

Pipe Material: Clay



Pipe Invert Elevation: 847.62 Ft

Pipe Invert Elevation: 845.51 Ft



Description

E7-078

Details

ID
E7-078

Status
Found

Rim Elevation
847.8673

Depth
5.08


Material
Block

AccessType
Standard

DropMH
No Drop

LocationDescription
Creek

vertGrade
Above



Description

E7-079

Details

ID
E7-079

Status
Found

Rim Elevation
856.2398

Depth
6.54

Material
Block

AccessType
Standard

DropMH
No Drop

LocationDescription
Paved Street

VertGrade
Even



3

Manhole



I want to...



Description

E7-081

Details

ID

E7-081

Status

Found

Rim Elevation

855.4993

Depth

7.62

Material

Block

AccessType

Standard

DropMH

No Drop

LocationDescription

Paved Street

vertGrade

Even

4



I want to...

Description

E7-084

Details

ID

E7-084

Status

Found

Rim Elevation

862.358

Depth

6.58

Material

Block

AccessType

Standard

DropMH

No Drop

LocationDescription

Curb/Ditch

VertGrade

Even



5

Description

E7-085

Details

ID
E7-085

Status
Found

Rim Elevation
869.7454

Depth
10.63

Material
Block

AccessType
Standard

DropMH
No Drop

LocationDescription
Driveway

vertGrade
Even



6

Description

E7-087

Details

ID

E7-087

Status

Found

Rim Elevation

863.6394

Depth

6.47

Material

Block

AccessType

Standard

DropMH

No Drop


LocationDescription

Curb/Ditch

VertGrade

Even

7



Manhole

Description

E7-088

Details

E7-088

Status
Found

Rim Elevation
853.1269

Depth
5.53


Material
Precast

AccessType
Standard

DropMH
No Drop

LocationDescription
Backyard

VentGrade
Even



8

Manhole

Description

E7-090

Details

ID

E7-090

Status

Found

Rim Elevation

869.9578

Depth

9.72

Material

Block

AccessType

Standard

DropMH

No Drop

LocationDescription

Paved Street

vertGrade

Even



I want to...



9

Description

E7-091

Details

ID

E7-091

Status

Found

Rim Elevation:

870.6666

Depth

7.57

Material

Block

AccessType

Standard

DropMH


No Drop

LocationDescription

Paved Street

vertGrade

Even



10

Manhole

Description

E7-092

Details

ID

E7-092

Status

Found

Rim Elevation

875.7298

Depth

7.84

Material

Block

Access Type

Standard

Drop MH


No Drop

Location Description

Alley

Vert Grade

Even



Manhole



I want to...



Description

E7-100

Details

ID

E7-100

Status

Found

Rim Elevation

880.3045

Depth

10.73

Material

Block

AccessType

Standard

DropMH

No Drop

LocationDescription

Curb/Ditch

VertGrade

Even

12



Manhole

Description

E7-101

Details

ID

E7-101

Status

Found

Rim Elevation

880.0213

Depth

9.89

Material

Block

AccessType

Standard

DropMH

No Drop


LocationDescription

Curb/Ditch

vertGrade

Even

13



Manhole

Description

E7-102

Details

ID
E7-102

Status
Found

Rim Elevation
885.8337


Depth
8.1

Material
Block

AccessType
Standard

DropMH
No Drop

LocationDescription
Paved Street



14

Manhole

Description

E7-104

Details

ID

E7-104

Status

Found

Rim Elevation

883.0975

Depth

12.2

Material

Block

AccessType

Standard

DropMH

No Drop


LocationDescription

Paved Street

vertGrade

Even

15



Description

E7-105

Details

D
E7-105

Status:
Found

Rim Elevation
381.0544

Depth
12.05

Material
Block

Access Type
Standard

Drop/MH
No Drop

Location Description
Paved Street

Vert Grade
Even



He

Manhole



I want to...



Description

E7-107

Details

ID
E7-107

Status
Found

Rim Elevation
878.433

Depth
7.4

Material
Block

AccessType
Standard

DropMH
No Drop

LocationDescription
Paved Street

VertGrade
Even

17

Manhole



I want to...

Description

E7-108

Details

ID

E7-108

Status

Found

Rim Elevation

874.2306

Depth

11.3

Material

Block

AccessType

Standard

DropMH


No Drop

LocationDescription

Paved Street

VertGrade

Even



18

Description

E7-109

Details

ID

E7-109

Status

Found

Rim Elevation

869.0416

Depth

5.48

Material

Block

AccessType

Standard

DropMH

No Drop


LocationDescription

Paved Street

vertGrade

Even

19



Manhole



I want to...

Description

E7-115

Details

ID

E7-115

Status

Found

Rim Elevation

870.1473

Depth

6.02

Material

Block

AccessType

Standard

DropMH

No Drop

LocationDescription

Unpaved Street

vertGrade

Even



20

Manhole



I want to...

Description

E7-124

Details

ID

E7-124

Status

Found

Rim Elevation

855.2385

Depth

11.73

Material

Block

AccessType

Standard

DropMH

Outside Drop

LocationDescription

Paved Street

vertGrade

Even



21

Manhole

Description

E9-011

Details

ID

E9-011

Status

Found

Rim Elevation

873.5388

Depth

7.52

Material

Brick

AccessType

Standard

DropMH


No Drop

LocationDescription

Backyard

VertGrade

Above



22

Description

E9-012

Details

ID

E9-012

Status

Found

Rim Elevation

869.3352

Depth

6.44

Material

Brick

AccessType

Standard

DropMH

No Drop

LocationDescription

Backyard

VertGrade

Even

23



WIDEN DITCH

Description

E9-014

Details

ID

E9-014

Status

Found

Rim Elevation

866.6588

Depth

6.4

Material

Block

AccessType

Standard

DredMH

No Drop


LocationDescription

Curb/Ditch

VertGrade

Even

24



Description

E9-015

Details

ID

E9-015

Status

Found

Rim Elevation

868.8272

Depth

5.68

Material

Block

AccessType

Standard


DropMH

No Drop

LocationDescription

Backyard

vertGrade



25

Description

E9-020

Details

ID

E9-020

Status

Found

Rim Elevation

866.7419

Depth

7.48

Material

Brick

AccessType

Standard

DropMH

No Drop

LocationDescription

Paved Street

VertGrade

Even



26

Description

E9-021

Details

ID
E9-021

Status
Found

Rim Elevation
864.8624

Depth
7.39

Material
Brick

AccessType
Standard


DropMH
No Drop

LocationDescription
Paved Street

VertGrade
Even

Vertical Grade Difference

27



Manhole



I want to...

Description

E9-027

Details

ID

E9-027

Status

Found

Rim Elevation

878.8636

Depth

7.85

Material

Brick

AccessType

Standard

DropMH

No Drop

LocationDescription

Paved Street

vertGrade

Even



28



